



www.sealey.co.uk

Cutting & Grinding Disc (PTC Series)

PRECAUTIONS ON THE USE OF ABRASIVE GRINDING WHEELS

Always ensure that the spindle speed of the machine is no higher than the operating speed marked on the wheel.

Visually inspect all wheels before mounting for possible damage in transit or during manipulation.

After mounting the wheel, always check to ensure that there is no free space between the operating spindle and the blocking rind, to prevent the wheel wobbling. Allow newly mounted wheels to run at operating speed, with guard in place for a few seconds before cutting and grinding.

Ensure there is a safety guard in place before operating the machine.

Always follow the indications marked on the wheel and check that the disc type you are using is suitable for the material.

ATTENTION: Cutting discs must be used for cutting only.

Always wear eye protection.

If used incorrectly, this product can cause damage or injury to operator.