


## Parts Information: Adjustable Height Plasma Cutting Table/ Workbench with Castor Wheels Model No: PCT2



| Item | Part No. | Description  |
|------|----------|--|
| 1    | PCT2.01  | Removable Side Handle  |
| 2    | PCT2.02  | Main Beam, A   |
| 3    | PCT2RS   | Replacement Slats (Pack of 10) - <b>Please see Catalogue</b> |
| 4    | PCT2.04  | Main Beam, B   |
| 5    | PCT2.05  | Funnel Side Plate, A   |
| 6    | PCT2.06  | Funnel Side Plate, B   |
| 7    | PCT2.07  | Foot Support, A  |
| 8    | PCT2.08  | Drawer Support, A  |
| 9    | PCT2.09  | Drawer   |
| 10   | PCT2.10  | Wheel (c/w Brake)  |
| 11   | PCT2.11  | Drawer Support, B  |
| 12   | PCT2.12  | Platform Base  |
| 13   | PCT2.13  | Foot Support, B  |

| Item | Part No. | Description                   |
|------|----------|-------------------------------|
| 14   | PCT2.14  | Support Beam                  |
| 15   | PCT2.15  | Foot Link                     |
| 16   | SS1025.S | Hex Head Set Screw M10 x 25mm |
| 17   | SWM10.S  | Spring Washer M10             |
| 18   | SN10.S   | Steel Nut M10                 |
| 19   | SS1040.S | Hex Head Set Screw M10 x 40mm |
| 20   | PCT2.20  | Button Head Screw M8 x 25mm   |
| 21   | SWM8.S   | Spring Washer M8              |
| 22   | SN8.S    | Steel Nut M8                  |
| 23   | SS830.S  | Hex Head Set Screw M8 x 30mm  |
| 24   | PCT2.24  | Foot Support Pin              |
| --   | PCT2-FK  | Fixing Kit (Not Shown)        |

**NOTE:** It is our policy to continually improve products and as such we reserve the right to alter data, specifications and component parts without prior notice. There may be alternative versions of this product, please contact us should you require this information.

**IMPORTANT:** No liability is accepted for incorrect use of product. Spare parts must be fitted by a competent person

**WARRANTY:** Guarantee is 12 months from purchase date, proof of which will be required for any claim.