


Parts Information:

Wheel Removal Trolley 500kg Premier Viking

Model No: W50T



| Item | Part No. | Description |
|------|-------------|---|
| 1 | 100/6000100 | BASE FRAME AND UPRIGHT SUPPORT |
| 2 | 100/6000400 | LIFTING FRAME |
| 3 | 100/02336 | BOLT |
| 4 | 100/6000700 | AXLE |
| 5 | 100/1000900 | AXLE FOR PIVOT WHEELS |
| 6 | 100/9032500 | HYDRAULIC UNIT |
| 7 | 100/02203 | CIRCLIP |
| 8 | 100/02204 | CIRCLIP |
| 9 | 100/6000800 | WHEEL |
| 10 | 100/0253300 | PIVOTING WHEEL C/W GALVANISED HOSE 99x39 |
| 11 | 100/02372 | PLASTIC PLUG |
| 12 | 100/01250 | COLLAR BUSHING |
| 13 | SN8.S | STEEL NUT M8 ZINC DIN934 (SINGLE) |
| | 100/02199 | JOINT LINK (NOT SHOWN) |

| Item | Part No. | Description |
|------|-------------|--|
| | 100/02200 | CHAIN (NOT SHOWN) |
| | 100/02205 | CIRCLIP (NOT SHOWN) |
| | 100/02293 | BALL 7.5mm dia (NOT SHOWN) |
| | 100/02359 | NYLON WHEEL (NOT SHOWN) |
| | 100/02425A | MOUNTING FOR HYDRAULIC PUMP (NOT SHOWN) |
| | 100/09003 | REPAIR KIT FOR PUMP (NOT SHOWN) |
| | W50TAC/RK | REPAIR KIT (AC HYDRAULIC UNIT) (NOT SHOWN) |
| | W50TO/RK | REPAIR KIT (ORIGO HYD. UNIT) (NOT SHOWN) |
| | 100/02039 | RELEASE SPRING (NOT SHOWN) |
| | 100/6000300 | WHEEL BOX (NOT SHOWN) |
| | 100/6000800 | WHEEL (NOT SHOWN) |
| | 100/02359 | NYLON WHEEL (NOT SHOWN) |
| | 100/6001500 | STEERING CYLINDER (NOT SHOWN) |

NOTE: It is our policy to continually improve products and as such we reserve the right to alter data, specifications and component parts without prior notice. IMPORTANT: No liability is accepted for incorrect use of product.

WARRANTY: Guarantee is 12 months from purchase date, proof of which will be required for any claim.

Sealey Group, Kempson Way, Suffolk Business Park, Bury St Edmunds, Suffolk. IP32 7AR



01284 757500



01284 703534



sales@sealey.co.uk



www.sealey.co.uk

Page 1 of 1 W50t Issue 2 DPL 17/01/18